

Installation and Troubleshooting Guide

NOTE: This installation is to be completed by an Authorized Dealer or Professional Service Technician. For questions regarding installation or warranty, call CDI Tech Support at 866-423-4832. Do not return to the Dealer or Distributor where the part was purchased. Contact CDI Electronics Directly for Return Materiel Authorization.


CDI P/N: 133-4558 Timer Base 3 Cyl.

Note: This unit replaces P/N's: 583395, 584558.

WARNING! This product is designed to be installed by a professional marine mechanic. CDI Electronics cannot be held liable for injury or damage resulting from improper installation, abuse, neglect or misuse of this product.

INSTALLATION

- 1. Disconnect the Negative battery cable.
- 2. Disconnect the old Timer Base.
- 3. Remove the flywheel, stator and old Timer Base.
- 4. Lubricate the inside area of the new Timer Base where the White slip ring goes and the area where the inside of the new Timer Base contacts the upper bearing carrier.
- 5. Install the White slip ring on the new Timer Base.
- 6. Compress the White slip ring and seat the new Timer Base into the bearing carrier.
- 7. Make sure the Timer Base is fully seated and secure the slip ring using the retainers removed during disassembly.



8. Remove the bushing link kit from the old Timer Base link arm and install it in the new Timer Base arm plate.

- 9. Connect the linkage to the new Timer Base.
- 10. Re-install the Stator and Flywheel according to the Service Manual.
- 11. Start and run the engine, adjusting the ignition timing according to the Service Manual.

TROUBLESHOOTING

Service Note: Please use the Factory recommended spark plug (Champion QL77JC4) gapped at 0.030".

NO SPARK ON ANY CYLINDER:

- 1. Disconnect the black yellow stop wire and retest. If the engine's ignition has spark, the stop circuit has a fault-check the key switch, harness and shift switch.
- 2. Disconnect the yellow wires from the rectifier and retest. If the engine now sparks, replace the rectifier.
- 3. Check the stator resistance. Reading should be about 500 ohms from the brown wire to brown/yellow wire.
- 4. Check the DVA output from the stator. You should have a reading of at least 150V or more from the brown wire to the brown/yellow wire (while connected to the pack) and 12 Volts on the Orange to Orange/Black power coil wires.
- 5. Check the resistance and DVA output of the Timer Base:

bolt the redebilitation and b with output of the rimor babon						
Read to	Reading	DVA (connected to pack)				
White	10-20 ohms	0.5 Volts Minimum				
White	10-20 ohms	0.5 Volts Minimum				
White	10-20 ohms	0.5 Volts Minimum				
	Read to White White	Read toReadingWhite10-20 ohmsWhite10-20 ohms	Read toReadingDVA (connected to pack)White10-20 ohms0.5 Volts MinimumWhite10-20 ohms0.5 Volts Minimum			

6. Check the DVA voltage on the Black/Yellow wire to engine ground. You should have a reading of at least 150V or more (while connected to the pack). If the reading is low, disconnect the stator 5 pin connector from the pack. Using a meter set to diode scale, check from the Black/Yellow wire to the Brown (and Brown/Yellow) wires. You should show a high or no reading at all. If you show a normal diode reading, the kill (Stop) diode is shorted and the pack needs to be replaced.

CDI Electronics, LLC • 353 James Record Road SW • Huntsville, AL 35824 USA

Web Support: www.cdielectronics.com • Tech Support: 1-866-423-4832 • Order Parts: 1-800-467-3371

All rights reserved. Reproduction or use of content, in any manner, without express written permission by CDI Electronics, LLC., is prohibited.

TEGRINIG/:



Installation and Troubleshooting Guide



NOTE: This installation is to be completed by an Authorized Dealer or Professional Service Technician. For questions regarding installation or warranty, call CDI Tech Support at 866-423-4832. Do not return to the Dealer or Distributor where the part was purchased. Contact CDI Electronics Directly for Return Materiel Authorization.

7. Check the resistance of the power pack SCR's:

Read from	Read to	Reading		
Blue Trigger wire	Orange/Blue	110 ohms*		
Purple Trigger wire	Orange/Green	110 ohms*		
Green Trigger wire	Orange	110 ohms*		
*Readings will vary slightly depending upon your meter. Readings should be fairly consistent.				

8. Check the kickback diodes connected to the power pack's SCR's, using a meter set to diode scale. If the readings show a short or open, replace the power pack and the ignition coil the Org wire was connected to.

Ŕ	ed meter lead	Black meter lead	Reading	
В	lack Ground wire	Orange/Blue	0.500**	
В	lack Ground wire	Orange /Violet	0.500**	
В	lack Ground wire	Orange/Green	0.500**	
**	The estual reading will very	depending upon your motor		

* The actual reading will vary, depending upon your meter.

9. Check the cranking RPM. A cranking speed of less than 250-RPM may not allow the system to fire properly.

NO SPARK OR INTERMITTENT ON ONE OR MORE CYLINDERS:

1. Check the resistance and DVA output of the Timer Base:

Read from	Read to	Reading	DVA (connected to pack)
Blue Trigger wire	White	10-20 ohms	0.5 Volts Minimum
Purple Trigger wire	White	10-20 ohms	0.5 Volts Minimum
Green Trigger wire	White	10-20 ohms	0.5 Volts Minimum

2. Check the DVA output on the orange wires from the power pack while connected to the ignition coils. You should have a reading of at least 150V or more. If the reading is low on one cylinder, disconnect the orange wire from the ignition coil for that cylinder and reconnect it to a load resistor. Retest. If the reading is now good, the ignition coil is likely bad. A continued low reading indicates a bad power pack or Timer Base (test per above).

Engine will not rev beyond 2500 RPM:

- 1. Use a temperature probe and verify that the engine is not overheating.
- 2. Disconnect the Tan temperature wire from the pack and retest. If the engine now performs properly, replace the temperature switch.
- 3. Make sure the Tan temperature switch wire is not located next to a spark plug wire.
- 4. If the engine will not rev above 2500 and the Tan wire is disconnected (and not near a spark plug wire), the pack is likely defective.