



Complete Mercury Distributor Trigger Assembly

134-3736

Distributor Trigger

994-4371

*Rotor Shaft for
4 and 6 Cylinder*

994-4603

*Rotor Shaft for
3 Cylinder*

213-6665

*Distributor Cap for
6 Cylinder*




(3 Cylinder Rotor Shaft)



(4 & 6 Cylinder Rotor Shaft)

**No longer available from the OEM
Providing the products to keep your boat on the water**

SHARK BITE!



CDI Electronics now provides new replacement components for the older Mercury Marine engines. The distributor trigger assembly uses the latest in magnetic-triggering technology. The steel rotor shafts are OEM compatible. The distributor cap is an exact replacement which reduces the potential of high-voltage discharges arcing to the engine ground. Detailed assembly instructions are included.

- Improved technology utilizing Hall-Effect magnetic design provides accurate and exact trigger pulses
- Trigger assembly includes new bearings, spacers, and detailed installation instructions
- Installation requires a steel triggering disk (included with the trigger assembly)
- Steel rotor shafts are exact replacement to the OEM (which are now NLA)
- Distributor pickup is molded to the shaft, reducing the potential for breakage
- New 6 cylinder distributor cap is manufactured from high dielectric material, thus reducing 'arcing to ground' issues
- 2 Year warranty from date of installation