


HP	Year	Sears Serial #/Model	Ignition
5	1973-1987	Engines manufactured by ESKA	R610851*
5	1988	225.58749, 225.587500, 225.587491, 225.587493.	185-2370
5	1989-1993	225.587501, 225.587502, 225.587503, 225.587504.	116-2379K 3
7.5	1973-1987	Engines manufactured by ESKA	110-0958
7.5	1988	225.581750, 225.581751, 225.581980.	185-2370
7.5	1989	225.581750, 225.581751.	185-2370
9.9	1973-1987	Engines manufactured by ESKA	110-0958
9.9	1986-1988	225.581980, 225.587990.	185-2370
9.9	1989-1993	225.581490, 225.581491, 225.581494, 225.581495, 225.581500, 225.581501, 225.581981, 225.581984, 225.581985, 225.581991, 225.581993, 225.581994, 225.581995, 225.601991, 225.587993.	116-2379K 2
9.9	1993-1/2-1994	225.581986, 225.581987, 225.581988, 225.581996, 225.581997, 225.581998	R819156T*
15	1980-1985	Engines manufactured by ESKA	110-0958
15	1986-1988	225.587150, 225.587151, 225.581490, 225.581500.	185-2370
15	1989-1993	225.581491, 225.581494, 225.581495, 225.581501, 225.581503, 225.581504, 225.581505, 225.584150, 225.584151, 225.602151, 225.582500, 225.582501.	116-2379K 2
15	1993-1/2-1998	225.581496, 225.581497, 225.581498, 225.581506, 225.581507, 225.581508, 225.591490, 225.591500.	R819156T*
25	1996-1998	225-582500, 225-582501, 225-582591, 225-592500, 225-592590.	R819156T*

* Item available on a Repair & Return basis only at this time.

SUZUKI OUTBOARD IGNITIONS



118-5320 2 Cyl CD Module

Replaces: 32900-95320




178-9550 Stator 3 Cyl (CALL FOR AVAILABILITY)

Fits 1983-1985 DT75 and 1979-1987 DT85
Replaces: 32100-95500 32101-95500



178-9450 Stator 4 Cyl (CALL FOR AVAILABILITY)

Fits 1981-1985 DT115 and DT140
Replaces: 32100-94500 32101-95500



158-9501 Rectifier

Replaces: 32800-95720 32800-95D00
32800-95D01

SHARK BITE: In some cases, CDI Electronics has the only ignition products available in the world for some engines.